



NARROWING THE PATH

lan Giammanco and Brenna Meisenzahl



A rotating column of air, in contact with the surface, pendant from a cumuliform cloud, and often visible as a funnel cloud and/or circulating debris/dust at the ground.



EF Rating	Character	3 Second Gust (mph)	Description
0	Weak	65-85	Light Damage . Branches broken off trees; shallow-rooted trees uprooted
1	Weak	86-110	Moderate Damage. Mobile homes pushed off foundations or overturned; roof surfaces peeled off
2	Strong	111-135	Considerable Damage. Mobile homes demolished; large trees snapped or uprooted
3	Strong	136-165	Severe Damage . Roofs and some walls torn from well-constructed houses; heavy cars thrown; trains overturned
4	Violent	166-200	Devastating Damage . Well-constructed homes leveled; structures with weak foundation blown some distance
5	Violent	Over 200	Incredible Damage. Strong frame houses lifted, carried considerable distances and disintegrated; auto-sized missiles airborne for several hundred feet or more


Thunderstorm Winds


Severe winds are reported most frequently of the 3 major hazards (wind, tornado, hail)

All types of thunderstorms can produce strong outflow winds


Strongest events can produce EF-0 to EF-2 damage severities

Thunderstorm Winds Scale





Outflow on Radar





Downburst & Microburst Damage Patterns

- Particularly strong downdrafts from thunderstorms
- Diverging damage pattern
- Surface wind gusts can reach 100+ mph
- Damage can be mistaken for tornado
- Hazardous for aircraft
- Very local and short lived










Building codes


CURRENT BUILDING CODES DO NOT CONSIDER TORNADOES EXCEPT FOR CRITICAL FACILITIES

THEY ARE BASED ON THUNDERSTORM AND NON-CONVECTIVE WINDS

HOWEVER MODERN CODES CAN REDUCE TORNADO DAMAGE AND INCREASE LIFE SAFETY







2011 Super Outbreak Alabama Tornadoes of April 26

Degree of Damage

- O Surveyed but no visible damage
- Visible damage threshold

Protects against water



Roof cover damage < 20%



Broken windows and/or





Significant roof cover loss, damage to garage doors, carport/porch roof structural damage



House shifted on foundation



- Roof structural damage, walls remain intact
- Exterior wall failure
- Most walls on lowest floor collapse
- All walls collapsed
- Complete destruction, slab swept clean

